Serial No.: 09/545,367

Amendment dated August 27, 2003 Reply to Office Action of June 27, 2003

Amendments to the Specification

Please replace paragraph beginning on page 8, line 23 with the following amended paragraph, where added material is shown in <u>underlined type</u>, deleted material is shown in <u>strikeout type</u>:

FIG. 3 shows yet another view of the transformer 100. In FIG. 3, the winding 52 on the second bobbin member 20 is shown more clearly. In this embodiment, a slot 26 is provided between two pin supports 95. The slot 26 allows the wire used for the winding 52 to start near the body portion of the bobbin member. Similar slots may be present on the first bobbin member. Also, as shown in FIG. 2 3, the second bobbin member 20 includes a recessed structure 83 for receiving a side-mounted printed circuit board (not shown). The recessed structure 83 is at a corner region of the second bobbin member 20.

Serial No.: 09/545,367

Amendment dated August 27, 2003

Reply to Office Action of June 27, 2003

Amendments to the Drawings:

The attached sheet of drawings includes changes to Figs. 16. and 17. This sheet, which

includes Figs. 16 and 17, replaces the original sheet including Figs. 16 and 17. As shown on the

attached annotated sheet, in Figs. 16 and 17, previously omitted reference characters 80, 81, and

83 have been added.

Attachment: Replacement Sheet

Annotated Sheet Showing Changes

Page 8 of 13